

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

GC905 **BAYSIDE FUEL OIL DEPOT CORP**
NW **1776 SHORE PKWY**
> 1 **BROOKLYN, NY 11214**
1.208 mi.
6377 ft. **Site 1 of 2 in cluster GC**

NY MOSF UST **1000382082**
NY Spills **NYD000811083**
RCRA NonGen / NLR
US AIRS
FINDS

Relative:
Higher

Actual:
2 ft.

MOSF UST:
Id/Status: 2-1600 / ACTIVE FACILITY
SWIS Code: 61
Facility Town: NEW YORK CITY
Contact Phone: (718) 372-9800
Emergency Contact: VINCENT ALLEGRETTI
Emergency Telephone: (718) 641-2052
CBS Number: Not reported
SPDES Num: 0-006297
Total Tanks: 6
Total Capacity: 2871000
Avg Throughput: 120000
License Stat: 1
Facility Type: STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Prod Xfer Options: AC
Expiration Date: 03/31/2005
Applic Rcvd: 01/31/2000
Operator: ANTHONY NATALE
Owner Name: ALFRED ALLEGRETTI BAYSIDE FUEL OIL DEPOT CORP.
Owner Address: 1776 SHORE PARKWAY
Owner City,St,Zip: BROOKLYN, NY 11214-
Owner Telephone: (718) 372-9800
Owner Type: Corporate/Commercial
Owner Status: 1
Owner Mark: First Owner
Mail To Name: BAYSIDE FUEL OIL DEPOT CORP.
Mail To Address: 1776 SHORE PARKWAY
Mail To Address 2: Not reported
Mail City,St,Zip: BROOKLYN, NY 11214-0002
Mail To Contact: ANTHONY NATALE
Mail To Telephone: (718) 372-9800
Legal Agent Name: ALFRED ALLEGRETTI
Legal Agent Address: 1776 SHORE PARKWAY
Legal Agent City,St,Zip: BROOKLYN, NY 11214-
Date Filed: 03/65
Latitude: 40|35|29
Longitude: 73|59|50

Tank ID: 1
Tank Location: UNDERGROUND
Install Date: 12/50
Capacity (Gal): 3000
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel

Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: Diking
Leak Detection: Groundwater Well
Overfill Protection: 24

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Dispenser: Suction
Test Date: 10/98
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 12/03/1998
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2000
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/16/1999
Federal Id No: Not reported
COI Date: / /

Tank ID: 2
Tank Location: UNDERGROUND
Install Date: 12/84
Capacity (Gal): 4000
Product: UNLEADED GASOLINE
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Impressed Current
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: Impressed Current
Second Contain: Diking
Leak Detection: In-tank System
Overfill Protection: 25
Dispenser: Suction
Test Date: 12/98
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 12/03/1998
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2000
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/16/1999
Federal Id No: Not reported
COI Date: / /

Tank ID: 3
Tank Location: UNDERGROUND
Install Date: 12/84
Capacity (Gal): 4000
Product: DIESEL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Impressed Current
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Pipe Internal: None
Pipe External: Impressed Current
Second Contain: Diking
Leak Detection: In-tank System
Overfill Protection: 25
Dispenser: Suction
Test Date: 12/98
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 12/03/1998
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2000
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/16/1999
Federal Id No: Not reported
COI Date: / /

Tank ID: A&B
Tank Location: UNDERGROUND
Install Date: 12/48
Capacity (Gal): 1260000
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner
Tank External: 13
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: Remote Impounding Area
Leak Detection: Groundwater Well
Overfill Protection: High Level Alarm
Dispenser: Submersible
Test Date: 12/96
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 12/03/1998
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2000
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/16/1999
Federal Id No: Not reported
COI Date: / /

Tank ID: D&C
Tank Location: UNDERGROUND
Install Date: 12/48
Capacity (Gal): 600000
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner
Tank External: 13
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: Remote Impounding Area
Leak Detection: Groundwater Well
Overfill Protection: High Level Alarm
Dispenser: Submersible
Test Date: 12/96
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 12/03/1998
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2000
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/16/1999
Federal Id No: Not reported
COI Date: / /

Tank ID: E&F
Tank Location: UNDERGROUND
Install Date: 12/57
Capacity (Gal): 1000000
Product: NOS 5 OR 6 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 13
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: Remote Impounding Area
Leak Detection: Groundwater Well
Overfill Protection: 32
Dispenser: Submersible
Test Date: 12/96
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 12/03/1998
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2000
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/16/1999
Federal Id No: Not reported
COI Date: / /

SPILLS:

Name: EKLOG MARINE E16 TANK BA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Address: 1776 SHORE PKWY.
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 8804718 / 1988-08-29
Facility ID: 8804718
Facility Type: ER
DER Facility ID: 236388
Site ID: 291959
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 2401
Spill Date: 1988-08-29
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1988-08-29
CID: Not reported
Water Affected: GRAVESEND BAY
Spill Source: Vessel
Spill Notifier: Responsible Party
Cleanup Ceased: 1988-08-29
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1988-08-31
Spill Record Last Update: 1988-08-31
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "VALVE VIBRATED OPEN DURING FUEL TRANSFER, CLEAN-UP IN PRGRESS, NYFD ALSO NOTIFIED."

All Materials:

Site ID: 291959
Operable Unit ID: 919828
Operable Unit: 01
Material ID: 456647
Material Code: 0001A

Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 25.00
Units: G
Recovered: .00
Oxygenate: Not reported

RCRA NonGen / NLR:

Date form received by agency: 2007-01-01 00:00:00.0
Facility name: BAYSIDE FUEL OIL DEPOT CORP
Facility address: 1776 SHORE PKWY
BROOKLYN, NY 11214-6598

EPA ID: NYD000811083
Mailing address: SHORE PKWY
BROOKLYN, NY 11214

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Contact: Not reported
Contact address: SHORE PKWY
BROOKLYN, NY 11214
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: ALFRED ALLEGRETTI
Owner/operator address: 1776 SHORE PKWY
BROOKLYN, NY 11214
Owner/operator country: US
Owner/operator telephone: 718-372-9800
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: TEXACO - U.S.A.
Owner/operator address: 1040 KINGS HWY P.O. BOX 5008
OPERCITY, NJ 99999
Owner/operator country: US
Owner/operator telephone: 609-667-3800
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

Date form received by agency: 2006-01-01 00:00:00.0
Site name: BAYSIDE FUEL OIL DEPOT CORP

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Classification: Not a generator, verified

Date form received by agency: 1999-07-08 00:00:00.0
Site name: BAYSIDE FUEL OIL DEPOT CORP
Classification: Not a generator, verified

Date form received by agency: 1998-04-06 00:00:00.0
Site name: BAYSIDE FUEL OIL DEPOT CORP
Classification: Small Quantity Generator

Date form received by agency: 1980-11-19 00:00:00.0
Site name: BAYSIDE FUEL OIL DEPOT CORP
Classification: Not a generator, verified

Hazardous Waste Summary:

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

US AIRS MINOR:

Envid: 1000382082
Region Code: 02
Programmatic ID: AIR NY0000002610600047
Facility Registry ID: 110001570675
D and B Number: Not reported

Primary SIC Code: 5171
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:

Region Code: 02
Programmatic ID: AIR NY0000002610600047
Facility Registry ID: 110001570675
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-05-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:

Registry ID: 110001570675

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110001570675

Environmental Interest/Information System:

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

HAZARDOUS AIR POLLUTANT MAJOR

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Registry ID: 110070241345

Facility URL: http://ofmpub.epa.gov/enviro/fii_query_detail.disp_program_facility?p_registry_id=110070241345

Environmental Interest/Information System:

GASOLINE AND DIESEL PRODUCERS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.